

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tom L. Ingram	8. Farm or Lease Name Craig A
3. Address of Operator POB 1757, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER H 2310 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 12S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Gladiola-Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3890.7 GR	12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/26/73-5/31/73

Set cast-iron bridge plug @ 9000'. Put 35' of cement @ 9000'-8965'. Cut 5 1/2" casing @ 4520' and pulled. Put 50 sack plug from 4570-4450' in and out of stub of 5 1/2" casing and in and out of base of 8-5/8" casing. Cut 8-5/8" casing @ 2028', 1498' and 1028'. Pulled 8-5/8" casing from 1028'. Put 50 sack plug from 1130'-1030'. Set 75 sack plug from 440'-340' in and out of base of 13-3/8" casing. Set 10 sack plug @ surface. Set Dry Hole Marker. Mud-laden brine water used between all plugs. Will notify when surface clean-up is complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Tom L. Ingram</u>	TITLE <u>Operator</u>	DATE <u>9/10/73</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		