

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K5919

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Salt Water Disposal	7. Unit Agreement Name
2. Name of Operator Jan Oil Company	8. Farm or Lease Name Aztec State
3. Address of Operator P.O. Box 95226, Oklahoma City, Oklahoma 73109	9. Well No. 1
4. Location of Well UNIT LETTER H, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 135 RANGE 32E NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4293 GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set DR plug in Baker model D packer and cap with ~~2000'~~ 35' cement.
- Cut 5-1/2" casing at free point.
- Run tbg. to csg. stub & spot 40 sack plug.
- Pull tbg. to 5390' & spot 40 sack plug from 5390' to 5290'.
- Pull tbg. to 4085' & spot 55 sack plug from 4085' to 3985' across 8-5/8" csg. shoe.
- Cut 8-5/8" csg. at free point - pull & lay down.
Note: If 8-5/8" csg. is recovered below 2000', a cement plug must be put in to protect the salt at 2000'.
- Run tbg. to 8-5/8" csg. stub & place 75 sack plug.
- Pull tbg. to 423' & pump a 85 sack plug from 423' to 323' across 13-3/8" csg. shoe.
- Place 10 sack surface plug & install Dry Hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. C. Bontary TITLE Agent DATE 10-7-77

APPROVED BY _____ TITLE _____ DATE 1977
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

10/11/77

10/11/77