

7-6-79

Attachment to C-101

State "27" Well No. 1

5. Treat perforations 5068'-5276' with 1500 gal 15% HCL. Test.
6. If significant oil is recovered, pumping equipment will be installed.  
If work is not successful, subsequent approval to plug and abandon well  
will be requested utilizing the plugs set in this workover as sufficient  
to meet State plugging requirements.