

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
E-2490

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator Exxon Corporation	8. Farm or Lease Name N.M. "CH" State
3. Address of Operator Box 1600, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>O</u> , <u>1,980</u> FEET FROM THE <u>East</u> LINE AND <u>760</u> FEET FROM THE <u>South</u> LINE, SECTION <u>27</u> TOWNSHIP <u>12-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat West Ranger Lake Dev
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU Baber Well Service Unit 6-18-73.
- Circ hole w/mud - pulled 413 jts 2" tbg.
- CI Bridge Plug hung at 4437'. Knocked plug loose, ran tbg to 9548', spotted 35 sx cmt plug.
- Cut 4-1/2" csg at 6215', pulled 194 jts spot 35 sx cmt plug at 6250', spot 35 sx cmt plug at 5669', and 35 sx cmt plug at 4317'.
- Cut 8-5/8" csg at 879' and pulled. Spot 70 sx cmt plug at 951' and another plug at 433'. 10 sx plug at surface.
- Installed dry hole marker as required by NMOCC.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. B. Beard TITLE Unit Head DATE 10-2-73
APPROVED BY Nathan E. Clegg TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: