| DISTRIBUTION SANTA FE   | STRIBUTION   |   |  |          |                               | Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 |  |  |
|---|--|---|--|----------|-------------------------------|--|--|--|
| FILE U.S.G.S. LAND OFFICE   | ¬  | MEXICO OIL CONO   | ENVATION COMM  | 1001011  | Sa. Indicate Type             | of Lease   |  |  |
| OPERATOR  |  |   |  |          | State X                       | Fees Lease No.   |  |  |
| SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  SER NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "TAPPL TATION FOR PERMIT L" (FORM C-101) FOR SUCH PROPOSALS.) |  |   |  |          |                               |  |  |  |
| I.  GII GAS WELL X  | OTHER-   |   |  |          | 7. Unit Agreement             | t Name   |  |  |
| 2. Name of Operator  TEXAS PACIFIC OIL OU.  | _ TNC.   |   |  |          | 8, Farm or Lease              |  |  |  |
| s. Affiress of Operator P. O. Box 1669 - Hobb   |  |   |  |          | ), Well No.                   | -  |  |  |
| 4. Location of Well   |  |   |  |          | 10. Field and Poc             |  |  |  |
| THE CASE LINE, SECT   |  |   |  |          |                               | r reng   |  |  |
|   | 15, Ele  | vation (Show whether  | DF. RT, GR, etc.)                                    |          | 12. County                    |  |  |  |
| Te. Check   | Appropriate Bo   | ox To Indicate N  | 161 DF   |          |                               | <u> </u>   |  |  |
|   | NTENTION TO:   |   | deure of Notice                                      |          | IT REPORT OF:                 |  |  |  |
| PERFORM REMEDIAL WORK  TEMPOFABILY ABANDON  PULL OR ALTER CASING  |  | LUG AND ABANDON   | REMEDIAL WORK  COMMENCE OR;LLING  CASING TEST AND CE |          |                               | NG CASING  |  |  |
| STHER   |  |   | OTHER  |          |                               |  |  |  |
| 17. Describe Fragosed or Completed C  | Clarel   |   | .,,  | . 7      |                               |  |  |  |
| 1. Hoved in casing pr 2. Displaced well flo 3. Set CIBP @ 10,035 4. Out off 5-1/2" cas 5. Out off 8-5/8" cas 6. Set 10' plug at so 7. Waiting on location   | uids with 9. ' and capped<br>sing (44757'<br>sing (*1065'<br>urface. Set | 54 mud.<br>w/5 sk cemen<br>Pulled and<br>Pulled and<br>dry hole mar | t on top. D<br>layed down.                           | Set 25 a | buids w/mud.<br>c cament plug | e cut off.   |  |  |
| 18.1 hereby certify that the information<br>Original Sign<br>Claude Aube  | ed by  | complete to the best o  | f my knowledge and l                                 |          | OATE1                         | -3-72  |  |  |
| APPROVED BY Alkan (CONDITIONS OF APPROVAL, IF AND   | ? lleg   | 19 milia  |  | . :      | DATE                          | 24 33 10   |  |  |