

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-23064
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-4860
7. Lease Name or Unit Agreement Name BAUM 'C' STATE
8. Well No. 1
9. Pool name or Wildcat BAUM UPPER PENN
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4280' KB

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CACTUS OPERATING CO, LLC
3. Address of Operator 1907 W. JEFFERSON AVE, LOVINGTON, NM 88260	4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>13S</u> Range <u>33E</u> NMPM <u>LEA</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PLUGGING UNIT. POOH & LB RODS, PUMP. Pull TUBING. SET CIBP @ 9740'. DUMP BAIL 25 SX CMT. TOC @ 9517'. Cut & Pull 5350' 5 1/2" CASING. RT36. SPOT 25 SX CMT 7662' TO 7422'. SPOT 50 SX CMT @ 5401'. TAGGED. SPOT 40 SX CMT 5401' TO 5261'. TAGGED. SPOT 40 SX CMT FROM 4083' TO 3986'. TAGGED. SPOT 50 SX CMT FROM 912' TO 760'. TAGGED. SPOT 60 SX CMT FROM 438' TO 408'. TAGGED. SPOT 60 SX CMT FROM 408' TO 307'. TAGGED. SPOT 10 SX CMT FROM 30' TO SURFACE. INSTALL DRY HOLE MARKER. CIRCULATE 10# MUD. WELL P+AD ON 7.13.01

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William V Palmer TITLE MANAGING MEMBER DATE 7.30.01  
TYPE OR PRINT NAME WILLIAM V PALMER TELEPHONE NO. 396.7560

(This space for State Use)

APPROVED BY GARY W WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 1 6 2003

CONDITIONS OF APPROVAL, IF ANY:

GWW