Submit 3 Copies to Appropriate District Office

CONDITIONS OF AFFROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088	WELL API NO. 30-025-23064
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. K-4860
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Baum "C" State
1. Type of Well: OIL GAS WELL X WELL	OTHER	
2. Name of Operator		8. Well No.
MWJ PRODUCING COMPA	NY	9. Pool name or Wildcat
3. Address of Operator 400 W. Illinois - St	uite 1100 Midland, Texas 79701	7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7
	O Feet From The South Line and 660	
	Township 13S Range 33E	NMPM Lea County
Section 31	10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
NOTICE OF INT	· .	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLIN	NG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	casing test and cement JOB perf "B" zone & acidize X	
OTHER:	OTHER:	"B" zone & acidize X
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	stions (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any proposed
8/90: MI & RU PU. 3 9/90: Ran tbg & sea e, press to 2000 psi 0-9800' & 9810-9816' 0/90: Ran Baker Mode 000 gals 20% HCL ac	Removed W/H & puled 1" vent stall assy. Set Seal assy in Mode, ok. Spt'd 1000 gals 15% HCL 2 SPF w/4" OD csg gun. el R-3 pkr, SSN, CO & 311 jts & 50 7/8" 1.1 sp grav ball sea 5 BPM w/40 bbls 2% KCL flush w	l F @ 9861'. Loaded & circ ac. Perf'd "B" zone from 2-3/8" tbg. Swabbed. Acd lers @ 6 BPM @ 2200 psi. Ba
1-22: Swabbed 3/90: POOH, LD pkr. ressed R-3 pkr, CO & 00# tension & instal	Ran perf sub w/bull plug, 2 drifted 311 jts 2-3/8" seal led dual flange. Top of pkr @	jts 2-3/8" EUE T/P, BHA w/ ock tbg in well. Set pkr w/
	vent string, 4' sub, 2' sub & ll w/180 bbls wtr. Ran pump.	
I hereby certify that the information above is tru	and complete to the best of my knowledge and belief.	
SIGNATURE Q/h h	mePat Drexle	r-Agent DATE1/25/90
TYPE OR PRINT NAME		TELEPHONE NO.
	L SIGNED BY JERRY SEXTON STRICT I SUPERVISOR	DATE JAN 29 1490

RECEIVED

JAN 26 1990

OCD HOSS Stelled