STATE OF NEW MEXICO		
ENERGY AND MINERALS DEPARTMEN		
DISTRIBUTION	OIL CONSERVATION DIVISION	
JANTA FR	P. O. BOX 2088	Form C-103 - Revised 10-1-7:
FILE	SANTA FE, NEW MEXICO 87501	
U.3.G.S.		Su. Indicate Type of Lease
LAND OFFICE		State Foo
OPERATOR		5. Stale Off & Gas Lease No.
		L-986
BO NOT USE THIS FORM FUR FOR		
	7. Unit Agreement Nonie	
2. Name of Operator		d. Farm or Lease Nume
Amoco Production Com		
1. Address of Operator		9. Well No.
P. O. Box 68, Hobbs,	3, Weit 140.	
4. Location of Well		
UNIT LETTER P 6	60 South 660	10. Field and Pool, or Wildcat
	60 FEET FROM THE South LINE AND 660 FEET FRO	Baum Upper Penn
THEEast LINE, SECTION	18 TOWNSHIP 13-S RANGE 33-E	
MININI MARKANI	15. Elevation (Show whether DF, RT, GR, etc.)	<u> annun hillinn</u>
	4298' RDB	Lea
Check A NOTICE OF INT	ppropriate Box To Indicate Nature of Notice, Report or O SUBSEQUEN	ther Data
PERFORM REMEDIAL WORK	PLUG AND ABANDON AEMEDIAL WORK	ALTERING CASING PLUG AND ABANCONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
OTHER	OTHER	
17. Describe Processed or Completed Oper work; SEE RULE 1103.	rations (Clearly state all pertinent details, and give portinent dates, includin	g estimated date of starting any proposed
fluid level at 7000 f plug at 9828' and re- tested for 168 hrs. a and pump. Released t at 9755'. Pressure t	1-18-82. Pulled rods, pump, tubing, and ancho evable bridge plug at 9852'. Swabbed for 19 h t. Final fluid level at 9000 ft. Re-set the set the packer at 9755'. Moved out service un and pumped 551 BW. Moved in service unit 2-13-8 the retrievable bridge plug and packer. Re-set ested to 1000 and okay. Re-set the packer at service unit 2-18-82. Pump tested for 96 hrs.	rs. with initial retrievable bridge it 1-29-82. Pump 2. Pulled rods, t the bridge plug 9661' Pan rods

and 67 BW. Moved in service unit 3-2-82. Pulled packer and moved out service unit. Pump tested for 264 hr. and pumped 6 BO, 1032 BW, and 172 MCF. Moved in service unit 5-4-82. Pulled pumping equipment, tubing, and anchor. Re-set the retrievable bridge plug at 9650'. Set a packer at 9625. Pressured bridge plug to 1000 and okay. Re-set packer at 5938'. Pressured to 1000 psi and okay. Swabbed with a trace of oil. Perforated 5921' with 2 SPF. Set a cement retainer at 5815. Squeezed perf 5921' with 250 sacks class C. Drilled out cement and retainer to 5815'. Ran 2-3/8" tubing and released the retrievable bridge plug. Reset the bridge plug at 9755' with tubing landing at 9655'. Installed pumping equipment and moved out service unit 5-14-82. Pump tested for 168 hrs. and pumped 4 BO and 463 BW. Moved in service unit 6-25-82. Pulled rods and tubing. 0+4-NMOCD,H 1-HOU 1-SUSP 1-CLF (over)

18. I hereoy certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY	Assist. Admin. Analyst	DATE
CONDITIONS OF APPRODEIRIES ANSUPR.	TITLE	DATE JUL 1 4 1982

Pulled the retrievable as set a cast iron bridge plug at ./55'. Set a packer at 9620' and acidized with 1000 gal 15% HCL. Pulled packer. Ran tailpipe, anchor, and tubing. Tubing landed at 9740' and anchor set at 9645'. Ran rods and pump. Moved out service unit 6-30-82. Pump tested for 144 hr. and pumped 32 BO, 511 BW, and 366 MCF. Returned well to production.

CSP - Co - 31982) El \_\_\_\_\_2. ⊇CFiCE

.\*

;