						1/2
NO. OF COPIES RECEIVED			Hilling		Form C-103	"MAG
DISTRIBUTION			ापण ा ५ ह	TENTE OF	Supersedes Old C-102 and C-103 Effective 1-1-65	111/1/1/1/3
ANTA FE	N	IEW MEXICO OIL CONS				(1)
ILE	 		JUN 21) 7	25 DH	Facate Type of Lease	
J.S.G.S.			•	<23 IM.	Edicate Type of Lease	<u> </u>
AND OFFICE				<u> </u>		e
PERATOR				5.	State Oil & Gas Lease No.	
					OG 5217	
	SUNDRY NOTICE	S AND REPORTS ON	WELLS			11111
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)						
OIL GAS				7.	Unit Agreement Name	
WELL WELL	OTHER-					
Name of Operator				В.	Farm or Lease Name	
Sun Oil Company					w Mexico "R" Sta	te
, Address of Operator					Well No.	
P.	0.Box 2792, 0d	essa, Texas 7976	0		1	
Location of Well				10.	. Field and Pool, or Wildcat	
UNIT LETTER	1980 🛒	ET FROM THE West	LINE AND 660 FE	11	indesignated	
ONII LEITER	,	ET FROM THE	LINE AND FE	ET FROM		1777
THE South	32	township 13	8 37 E			11111
LHE	INE, SECTION	TOWNSHIP	RANGE	_ имрм		11111
	15	Elevation (Show whether	DF, RT, GR, etc.)	12	. County	1111
		4143' Gr.			Lea	/////
<u>, , , , , , , , , , , , , , , , , , , </u>	Cl	·				77777
			ature of Notice, Report	or Other	Data	
NOTIC	CE OF INTENTION	TO:	SUBSE	QUENT RE	EPORT OF:	
_	ר	₁				
ERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
	=					
MPORARILY ABANDON			COMMENCE DRILLING OPNS.		PLUG AND ABANDONM	ENT
-		CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB	*	PLUG AND ABANDONM	ENT
<u> </u>		CHANGE PLANS	ř	X	PLUG AND ABANDONM!	ENT
OTHER]	CHANGE PLANS	CASING TEST AND CEMENT JOB	*	PLUG AND ABANDONM!	ENT
OTHER		arly state all pertinent deta	CASING TEST AND CEMENT JQB		mated date of starting any p	roposed
other Describe Proposed or Co work) SEE RULE 1103. On 6-14-69 re 24# J-55 8R 8	nn 8 5/8" OD ca ST&C #1 Cond., DO:. Cemented pature est. 820	sing. (21 jts. 2 1752.19' and (59 with 300 sks Inc F; est minimum f	CASING TEST AND CEMENT JQB	2 cond, ST&C, #1 3). Rul re 105°;	789.84'), 58 jts. cond., 1949.91' 107, Option 2;	roposed
other Describe Proposed or Cowork) SEE RULE 1103. On 6-14-69 re 24# J-55 &R Seated at 456 Mixing three of test	an 8 5/8* OD castac #1 Cond., Dot. Cemented patture est. 82% 850 psi. In p	sing. (21 jts. 2 1752.19' and (59 with 300 sks Inc F; est minimum f lace 12 hours pr	ils, and give pertinent dates, in 4# J-55 &R ST&C, #2 jts, 28# H-40, &R Sor 45 gel (501 ft. 2000)	2 cond, ST&C, #1 3). Rul re 105°; ed 8 5/8	789.84'), 58 jts. cond., 1949.91' e 107, Option 2: est. strength e 800#/30 min. o	roposed
OTHER Describe Proposed or Cowork) SEE RULE 1103. On 6-14-69 re 24# J-55 &R seated at 450 Mixing threat time of test	an 8 5/8* OD castac #1 Cond., Ot. Comented rature est. 82* 850 psi. In p	sing. (21 jts. 2 1752.19' and (59 with 300 sks Inc F; est minimum f lace 12 hours pr	ils, and give pertinent dates, in J-55 &R ST&C, #2 jts, 28# H-40, &R S or 45 gel (501 ft.) ornation temperatur for to test. Teste	2 cond, ST&C, #1 3). Rul re 105°; ed 8 5/8	789.84'), 58 jts. cond., 1949.91' e 107, Option 2: est. strength e 800#/30 min. o	roposed