5. spot 50 sx p 6. pull 8 5/8 c 7. spot 70 sx p 8. spot 70 sx p 9. spot 10 sx p 10. install dry	th mud & spot 50 sx polug @ 4470 woc & tag sg. est. 1000' olug @ 1050 woc & tag olug @ 420 woc & tag olug @ surf hole marker & clean l	plug	ſ.		-27-78 28 1978
3. pull 5½ csg. 4. load hole wi 5. spot 50 sx p 6. pull 8 5/8 c 7. spot 70 sx p 8. spot 70 sx p 9. spot 10 sx p 10. install dry	th mud & spot 50 sx polug @ 4470 woc & tag sg. est. 1000' olug @ 1050 woc & tag olug @ 420 woc & tag olug @ surf hole marker & clean l	ocation te to the best of my knowledge and believed.	ſ.		
3. pull 5½ csg. 4. load hole wi 5. spot 50 sx p 6. pull 8 5/8 c 7. spot 70 sx p 8. spot 70 sx p 9. spot 10 sx p	th mud & spot 50 sx polug @ 4470 woc & tag ssg. est. 1000' olug @ 1050 woc & tag olug @ 420 woc & tag olug @ surf	plug	ug		
3. pull 5½ csg. 4. load hole wi 5. spot 50 sx p 6. pull 8 5/8 c 7. spot 70 sx p 8. spot 70 sx p 9. spot 10 sx p	th mud & spot 50 sx polug @ 4470 woc & tag ssg. est. 1000' olug @ 1050 woc & tag olug @ 420 woc & tag olug @ surf	plug	ug		
3. pull 5½ csg. 4. load hole wi 5. spot 50 sx p 6. pull 8 5/8 c 7. spot 70 sx p 8. spot 70 sx p 9. spot 10 sx p	th mud & spot 50 sx polug @ 4470 woc & tag ssg. est. 1000' olug @ 1050 woc & tag olug @ 420 woc & tag olug @ surf	plug	ug		
3. pull 5½ csg. 4. load hole wi 5. spot 50 sx p 6. pull 8 5/8 c 7. spot 70 sx p 8. spot 70 sx p	th mud & spot 50 sx polug @ 4470 woc & tag ssg. est. 1000' olug @ 1050 woc & tag olug @ 420 woc & tag	plug	ug		
3. pull 5½ csg. 4. load hole wi	ith mud & spot 50 sx p	plug e 3030 woc a cay pi	ug		
		Jua 6 5950 Was 8 tag ni			
u orky see RULE 1103. 1. set cast iro	on plug @ 10,200 & dum				
OTHER	spleted Operations (Clearly state al.	l pertinent details, and give pertinent da	tes, including e	stimated date of st	tarting any proposed
FULL OR ALTER CASING	CHANGE PL		10'6		
PERFORM REMEDIAL WORK	PLUG AND	ABANDON XXX REMEDIAL WORK			NG CASING
	Check Appropriate Box To E OF INTENTION TO:	Indicate Nature of Notice, Re	=	r Data REPORT OF:	
	15. Elevation (4146	Show whether DF, RT, GR, etc.)		12. County Lea	
THE East CIN	e, section 8 towns	HIP 145 RANGE 34E	NMPNI.		
4, Location of Well		North LINE AND 766	FEET FROM	Cerca, Per	
420 N. Shipp, Ho				9, Well No. 1	
Jamison & Caffey, Inc.				8. Farm or Lease Name Tenneco st	
OIL XX GAS WELL		-1017 FOR SUCH PROPUSACS.		7. Unit Agreement	Name
IDO NOT USE THIS FOR	SUNDRY NOTICES AND RE	PORTS ON WELLS PLN OR PLUG BACK TO A DIFFERENT RESERV	DIR.	K544	
				5, State Oil & Gas	Lease No.
OPERATOR			[]	State XX	Fee
LAND OFFICE			1 -	a, Indicate Type o	4.5.
U.S.G.S. LAND OFFICE					
	NEW MEXICO	OOL CONSERVATION COMMISSIO	N	C-102 and C-10 Effective 1-1-65	