

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

RECORDS OFFICE D. 0000  
 DEC 17 1 23 PM '69

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease  
 State  Fee   
 5. State Oil & Gas Lease No.  
 B-10209

SUNDRY NOTICES AND REPORTS ON WELLS  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas American Oil Corporation	8. Farm or Lease Name Sinclair-State
3. Address of Operator 1012 Midland Savings Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> FEET FROM THE <u>South</u> LINE AND <u>2210</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>13S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Lazy J
15. Elevation (Show whether DF, RT, GR, etc.) 4273' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Propose to:
1. Pull tubing and packer.
  2. Set retrievable bridge plug at 9710'.
  3. Perforate additional zone 9686 - 9692'.
  4. Acidize with approx. 2500 gals.
  5. Swab and/or flow-test.
  6. Retrieve bridge plug.
  7. Install pumping equipment to produce from perfs. 9720-26' & 9686-92'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jawaman TITLE Production Superintendent DATE December 16, 1969

APPROVED BY Leslie A. Clements TITLE Oil & Gas Inspector DATE DEC 18 1969

CONDITIONS OF APPROVAL, IF ANY: