

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-6508	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Dry Hole		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
BTA Oil Producers		Keith 707 JV-D
3. Address of Operator		9. Well No.
104 South Pecos, Midland, Texas 79701		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM		Baum Upper Penn
THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>14-S</u> RANGE <u>32-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4305 KB		Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

Set CIBP @9814' w/20' cmt. on top.
Cut & pulled 5½" csg @ 4274'.
25 sx @ 4274' (5½" csg stub)
Cut & Pulled 8-5/8" csg @ 2500'
25 sx @ 2500' (8-5/8" csg stub)
25 sx @ 408' (11-3/4" shoe)
10 sx @ surface
Installed dry hole Marker
Plugged & Abandoned 4-26-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. D. Boyce TITLE Production Clerk DATE 5/4/71

APPROVED BY Nathaniel H. King TITLE OIL & GAS INSPECTOR DATE SEP 5 1972

CONDITIONS OF APPROVAL, IF ANY: