NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	The west of a conservation commission	Effective 1-1-65
U,S.G.S,		
LAND OFFICE		5a, Indicate Type of Lease
		State X Fee
OPERATOR		5. State Off 6 Gas Lease No.
		06-1516
SUNDE	RY NOTICES AND REPORTS ON WELLS	THE THINK
(DO NOT USE THIS PORCE FOR PRICAL	REPOSALS TO CHILL OR TO CLEPTA OR PUBLICACE TO A DIFFERENT RESERVOIR.	
1.	(FORM CHOT) FOR SUCH PROPOSALS,)	
OIL AS WELL	,	7. Unit Agreement Name
2. Nacie of Operator	OTHER-	<u> </u>
		8. Farm or Lease Name
TEXACO Inc.		N.M. DM'St. NCT-1
), Address of Operator		9. Well No.
P. O. Box 728.	Hobbs, New Mexico 88240	
, Location of Well		10. Field and Pool, or Wildcat
UNIT LETTERM	990 South	
VIVI CEPTER	990 FEET FROM THE South LINE AND 660 FEE	ET FROM LAZY J Penn
**4	· · · · · · · · · · · · · · · · · · ·	
THE WEST LINE, SECTI	ION 21 TOWNSHIP 13-S RANGE 33-E	_ NMPM. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Les
Check	Appropriate Box To Indicate Nature of Notice, Report	
NOTICE OF IN		
	SUBSEC	QUENT REPORT OF:
PERFORM REMEDIAL WORK		_
7	PLUG AND ABANDON KEMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
7 Deposible Deposit at Company		
work) SEE RULE 1703.	perations (Clearly state all pertinent details, and give pertinent dates, inc	
		OTIFIED 2 NING OF
1. Set CIBP at 96	50' with 35' (5 sx.) cement on top.	의 10 년 10
		<b>ビジ</b> し
2. Load hole with	mud (25 sx gel per 100 bbls. water,	hadra an analysis OZE
wherever possi	bla)	prime or produced, ZZ-
Wildrever Possi	rote).	BEGINE FOR
3. Run free point	man milit and a man	<del>-</del>
5. Run free point	c. Cut 52" casing and pull.	:S H さ
h o	· · · · · · · · · · · · · · · · · · ·	<b>₹</b> F o
4. Spot 100' (35	sx) cement plug across casing atub.	THE COMMISSION MUST PUCGING OPERATIONS F
		shoe at 4146'. Silva on the state of the sta
5. Spot 100' (40	sx)cement plug across 8-5/8" casing s	those at Julies See
6. Run free point	. Cut 8-5/8" Casing and pull.	¥ = 0 \$
	out only country and putt.	ပည <i>်း</i> ကြောင်း
7. Spot 100' (70	av amout when a construction	~ \$ \$ <b>%</b>
1. phon 700. (10	sx) cement plug across casing stub.	THE CO. FOURS. TO BE A
8. Spot 100' (70		
o. spot 100, (40)	sx) cement plug across 11-3/4" casing	shoe at 363'.
9. Spot 20' (10 s	x) cement plug at surface.	Expires 10/1/16
IU. Install marker	and clean location	O granica
I hereby certify that the information a	above is true and complete to the best of my knowledge and belief.	
William Contraction of the Contr		
NED TO THE TOTAL PROPERTY OF THE PARTY OF TH	1// /	•
July Colly	Miss. Asst. Dist. Supt.	DAYE 8-11-76
		8123 4 20-
	TO THE RESERVE OF THE PROPERTY	A Section 19 And Annual Property (1997)
The Later of the L	Colg. Marine Colg.	A446 J 3 7975
PHOVED BY	John Berner	AUG 19 1978

\* note on back side -

1 = 121976

12, 100' pluy top Abo 25 15 mt behil pyo 12, 100' pluy top cloucts at 5422 = 15 mt behil pyo 12, 100' pluy top cloucts at 1788 = 15 mt behil pyo