

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator SUN OIL COMPANY		8. Farm or Lease Name NEW MEXICO U.	
3. Address of Operator P. O. Box 1861, Midland, Texas 79701		9. Well No. 1	
4. Location of Well UNIT LETTER D, 660 FEET FROM THE N LINE AND 660 FEET FROM THE W LINE, SECTION 34 TOWNSHIP 14-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat Tres Papalotes (Penn)	
15. Elevation (Show whether DF, RT, GR, etc.) 4109 GR		12. County Lea	

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2-29-72 Ran CIBP on wireline & set @ 10,200 w/3 sx cmt on top. Perf 5-1/2" csg @ 9912-9924, 2 shts/ft.
- 3-1-72 Acidize w/500 gals 15% NEHCL & swab.
- 3-4-72 Acidize pfs.9912-9924 w/5000 gals. 15% NEHCL. Swbd 8 hrs & rec 55 BLW, sli tr oil Prep to P&A
- 3-6-72 Lay 50 sx plug 9936-9436 & SD to move in csg puller.
- 3-22-72 C. E. Knight shot 5 1/2 csg @ 8500. Stuck. Shot @ 8000 & rec'd 238 jts.
- 3-25-72 Circ. 9.5 mud.
- 3-27-72 Lay 75 sx cmt plug 8000-7708, 75 sx plug @ 6100-5785 & 75 sx plug 4572-4310.
- 3-28-72 Put 10 sx plug 30' to surface. Install dry hole marker - P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles E. Gray TITLE Proration Clerk DATE 8-2-72

APPROVED BY Nathan E. Olegg TITLE Oil Conservation Officer DATE

CONDITIONS OF APPROVAL, IF ANY: