

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	<b>K-3572 &amp; K-701</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Taylor Pruitt</b>	8. Farm or Lease Name <b>High Plains</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>C</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1830</b> FEET FROM THE <b>West</b> LINE, SECTION <b>23</b> TOWNSHIP <b>14 S</b> RANGE <b>34 E</b> NMPM.	10. Field and Pool, or Wildcat <b>High Plains - Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4096.8 GR</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Plugged and abandoned 9:00 A.M. 8/8/70 as follows:**

25 sacks top Penn 10,320 to 10,235  
25 sacks top Welfcamp 9615 to 9530  
25 sacks top Abe 8080 to 7995  
50 sacks across 8 5/8" shoe 4511 to 4426  
Cut and pull 1617' of 8 5/8" casing,  
50 sacks @ 1687'  
25 sacks @ 404'  
10 sacks @ surface with regulation marker  
9.3# mud between all plugs.  
Location to be cleared, levelled and made ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>H. L. Smith</i></u>	TITLE <u>Agent</u>	DATE <u>8/11/70</u>
APPROVED BY <u><i>John W. Runyan</i></u>	TITLE <u>Geologist</u>	DATE <u>DEC 3 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		



RECEIVED

NOV 12 1970

OIL CONSERVATION COMM.  
HOES, H. L.