

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23619
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NM 3138
7. Lease Name or Unit Agreement Name	
Baum State 23704	
8. Well No.	2
9. Pool name or Wildcat	Baum Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4266' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator MWJ Producing Company 15439
3. Address of Operator 400 W. Illinois, Ste. 1100, Midland, TX 79701	4. Well Location SH: L 990 BH: N 1791 Feet From The West Line and 2310' 646' Feet From The South Line
5. Section 5 Township 14S Range 33E NMPM Lea County	6. Pool name or Wildcat Baum Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4266' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/30/92-MIRU Pride Pulling Unit.

02/03/92-RU Pride Wireline. Ran & set CIBP @10,100'. Dumped 5 sx cmt. Spotted 25 sx plug w/ mud f/7000-6900'.

02/04/92-Removed tbg head & welded on lift sub. RU csg jacks. Checked stretch on 5-1/2" csg.

02/05/92-Ran charge & cut csg @ 6027'. POOH w/5-1/2" csg.

02/06/92-Spotted 75 sx plug w/mud f/6080-5854'.

02/07/92-Tagged plug @ 5894'. Loaded hole w/mud. Spotted 60 sx plug f/4128-4010'.

02/08/92-Shot 8-5/8" csg off @ 794'. POOH w/8-5/8" csg. Spotted 105 sx plug f/844-693'.

02/10/92-Tagged plug @ 693'. Spotted 84 sx plug @ 412'. Tagged plug @ 302'. Spotted 15 sx at surface. Welded on dry-hole marker. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sabra Fury TITLE Agent DATE 3/19/92

TYPE OR PRINT NAME Sabra Fury TELEPHONE NO. 915/682-5216

(This space for State Use)

ORIGINAL SIGNED BY
JOHN W. ROSS
OIL & GAS INSPECTOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

AUG 28 1998

RECEIVED

MAR 20 1992

OCD HOBBS OFFICE