STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

March 23, 1992

BRUCE KING GOVERNOR

1E & TITLE

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-8161

MWJ Producing Company Attn: Sabra Fury
400 West Illinois, Suite 1100
Midland, TX 79701-2310
Gentlemen:
Form C-103, Report of Plugging, for yourBaum State #2-L Sec 5, T14S, R33E
cannot be approved until a Division representative has made an inspection of the location and found it to be cleared to comply with Division Rules and the work has been done.
() 1. All pits have been filled and levelled.
() 2. Rat hole and cellar have been filled and levelled.
() 3. A steel marker 4" in diameter and approximately 4' above ground level as been set in concrete. It must show the Operator. Lease Name, Well Number, Quarter/Quarter Section or Unit Designation, Section, Township and Range numbers which have been permanently stenciled or welded on the marker.
() 4. The location has been levelled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
() 5. The dead men and tie downs have been cut and removed.
) 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been levelled and cleared of all junk and equipment.
The above are minimum requirements and no plugging bond will be released intil all locations for plugged and abandoned wells have been inspected and forms C-103 approved. When all of the work outlined above has been done, lease notify this office by filling in the blank form below and retuning his letter to us so that our representative will not have to make more han one trip to the location.
IL CONSERVATION DIVISION
Que La
fry Saxton, Supervisor Dist I
LL IN BELOW AND RETURN
certify that the above work has been done and the
ready for your inspection and approval. LEASE WELL # UL-S-T-R
ERATOR

DATE

