## Memo

From EVELYN DOWNS Oil Conservation Staff Specialist

11/16/89

\* To WHOM IT MAY CONCERN

David Trejo with OCD data processing dept. in Santa Fe advised it was not necessary to post to ID report the recompletion by directionally drilling to a different bottomhole location since the well was still completed in the same pool and the new BHL was still within the 160-acre proration unit even though the tunit little of the BHL is  $\underline{N}$  unstand of  $\underline{L}$ .

Evelyn Downs