

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-23936
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-2043
7. Lease Name or Unit Agreement Name West Tres Papalotes Pen Unit
8. Well No. 311
9. Pool name or Wildcat Tres Papalotes Penn West

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Permian Resources, Inc. dba Permian Partners, Inc.
3. Address of Operator P. O. Box 590 Midland, TX 79702	4. Well Location Unit Letter <u>A</u> : <u>560</u> Feet From The <u>North</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>30</u> <u>31</u> Township <u>14S</u> Range <u>34E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Notified OCD on 01/16/98. Pumped 25 sxs. from 10,370-10,166' Tagged plug.
- Displaced well w/9.5 ppg. salt mud.
- Pumped 25 sxs. from 7000-6753'.
- Shot 5-1/2 csg. @ 4195'. Csg. not free. Notified OCD. Pumped 25 sxs. @ 4310-4087'. Tagged plug.
- Shot 5-1/2 csg. @ 2840'. POH & LD csg.
- Pumped 40 sxs. from 2902 - 2711'. Tagged plug.
- Pumped 30 sxs. from 2010 - 1856'.
- Shot 8-5/8 csg. @ 486'. POH & LD scg.
- Pumped 110 sxs. from 542 - 315'. Tagged plug.
- Pumped 10 sxs. from 30 - surface.
- Installed well marker & weld on cap. 1-23-98

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy Bruno TITLE Production Manager DATE 11/21/97
TYPE OR PRINT NAME Randy Bruno TELEPHONE NO. 915/685-0113

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

gk
CJ