

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-6933	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry		7. Unit Agreement Name
2. Name of Operator The Superior Oil Company		8. Farm or Lease Name State "P"
3. Address of Operator P. O. Box 1900, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER F, 1830 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 14-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) KB: 4166		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Shot 8-5/8" casing at 1448'. Pulled all 8-5/8" casing above shot point on 9-28-74.
- Placed a 50 sack cement plug from 1458'-1358'.
- Placed a 55 sack cement plug from 415'-315' (11-3/4" casing shoe at 405').
- Cut off 11-3/4" casing head and placed a 10 sack cement plug in top of 11-3/4" casing. Welded a 1/2" steel plate in top of 11-3/4" casing.
- Installed a dry hole marker in accordance with NMOCC rules.

PLUGGED & ABANDONED 9-28-74

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>O. V. Savage</u>	O. V. Savage	TITLE <u>Production Engineer</u>	DATE <u>November 5, 1974</u>
APPROVED <u>Nathan E. Clegg</u>		TITLE <u>Oil</u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED

NOV 7 1961

OIL CONSERVATION COMM.
HOBBBS, N. M.