

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-5301	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
(SEE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)

6. Indicate Type of Well		7. Unit Agreement Name
OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	
8. Name of Lessee		8. Farm or Lease Name
ELK OIL COMPANY		Etcheverry State
9. Address of Lessee		9. Well No.
P. O. BOX 310, ROSWELL, NEW MEXICO 88201		1
10. Location of Well		11. Field and Pool, or Wildcat
UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>520</u> FEET FROM		Tres Papalotes
THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>14S</u> RANGE <u>34E</u> N.M.P.M.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4220 Grd		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug & Abandon as follows:

1. Place cement across perms from 10,400-10,510'. *TAG PLUG*
2. Cut 4½" casing @ 9000', place 50 sx plug in & out of 4½" stub. *TAG PLUG*
3. Place 50 sx plug @ 6000' across Glorietta.
4. Shut in Wellhead.

Prepare well for Salt Water Disposal, pending Oil Conservation Commission hearing.

THE COMMISSION MUST BE NOTIFIED  
24 HOURS PRIOR TO COMMENCING WORK

I, hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>President</u>	DATE <u>10/15/81</u>
Orig. Signed by Les Clements Oil & Gas Insp.	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:

\* Min all plugs 100' - mud between all plugs.