

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24260
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-5301

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
ELK IOL COMPANY

3. Address of Operator
Post Office Box 310, Roswell, New Mexico 88202-0310

4. Well Location
Unit Letter P : 660 Feet From The South Line and 520 Feet From The East Line

Section 32 Township 14 South Range 34 East NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4110 GR

7. Lease Name or Unit Agreement Name Etcheverry State
8. Well No. <u>1</u>
9. Pool name or Wildcat Tres Papalotes

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:
Work performed in December, 1981

- 1) Set Cast Iron BP at 10,040', dumped 4 sxs cement (35').
- 2) Shot 4½" casing at 8550'; recovered 8550' of 4½" casing.
- 3) Loaded hole with mud.
- 4) Set 50 sxs plug in ! out of 4½ casing stub 8550'.
- 5) Set 40 sxs plug at 6000'; top of Glorieta.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 11/01/90
TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. (505)623-3190

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: