## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

		_
we. or torice sectives		
DISTRIBUTION		
BANTA FE		
FILE		
U.\$.G.\$.		
LAND OFFICE		
OPPRATOR	1	1

## OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088		Form C-103
BANTA PE	SANTA FE, NEW MEXICO 87501		Revised 10-1-78
FILE			5a, Indicate Type of Lease
U.\$.G.\$.	]	State X Foe	
LAND OFFICE			
PERATOR	_J		5. State Off & Gas Lease No.
			LG 1333
SUNDF	RY NOTICES AND REPORTS OF PLUG	N WELLS	
(DO NOT USE THIS FORM FOR PA USE "APPLICAT	OPOSALS TO CRILL OR TO DELPIN OR PLUG FION FOR PERMIT" (FORM C-101) FOR 5	BACK TO A DIFFERENT RESERVOIR. UCH PROPOSALS.)	
•			7, Unit Agreement Name
OIL X GAS WELL	other. Re-entry		
Name of Operator			8, Farm or Lease Name
Yates Petroleum Corporation		Midwest XV State	
Address of Operator			9. Well No.
207 South 4th St., Artesia, NM 88210			1
			10 Field and Pool, or Wildcat
. Location of well			
UNIT LETTER B 6	60 FEET FROM THE North	LINE AND 1980 FEET PAG	Saunders Permo-Upper Pen
East	10N19 TOWNSHIP	14s RANGE 33e NMPI	
THITTITT	15. Elevation (Show wheth	er DF, RT, GR, etc.)	12. County
	4262' GR		Lea
		N (N) D	
		Nature of Notice, Report or O	
NOTICE OF I	NTENTION TO:	SUBSEQUEN	IT REPORT OF:
	_		_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		Perforate, Acid	1ze X
DTHER		]	
	operations (Clearly state all pertinent d	letails, and give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.  10-25-83. Well swab	bed dry to seating nipp!	le. No oil or gas. Rig	down unit
		packer. Wash over bridg	
hole to 10039'. Set	packer 9970'. Prep to	perforate 10008-18'. Gu	n would not go thru
tuhing at seating ni	nnle POOH to perforate	ed via casing. TOOH w/br	idea plus and market
WIH and perforated 1	$0.008 - 18^{\circ}$ $1.000 \times 000$	s as follows: 10008-10'	// 1-1> 10012
1001/1/2 belock 100	16 and 100101 (4 halas)	BOOM D DDD	(4 noies); 10013 and
10014 (2 notes), 100	to and toolo (4 notes).	POOH. Ran RBP and pac	ker to 7323'. PUH
w/packer. Did not n	ave bridge plug. With W/	tubing and latched onto	RBP and pulled. RIH
w/bridge plug and se	t at 10050', tested to	3000#, OK. Set packer 99	64'. Acidized w/3000
gallons 15% acid and	5 ball sealers. Swabbi	ing back load. Made 20 sw	ab runs.
11-21-83. Rigged dow	n and moved off pulling	unit.	
	•		
	Chit have		
	· · · · · · · · · · · · · · · · · · ·		
18. I hereby certify that the information	n above in true and complete to the bei	et of mir knowledge and belief.	
f	· >> .		
Man Rose In	Don dette me	Production Supervisor	11-22-83
the state of the s			VALE
V			

o postanti

MO1 38 1983.

O.C.D. HOSES OFFICE 7