

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 24372
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. NA
7. Lease Name or Unit Agreement Name John Etcheverry, Jr. "A"
8. Well No. 2
9. Pool name or Wildcat Tres Papalotes Penn. West

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Re-entry</u>	
2. Name of Operator SAGE ENERGY COMPANY	
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	
4. Well Location Unit Letter <u>E</u> : <u>2080</u> Feet From The <u>North</u> Line and <u>560</u> Feet From The <u>West</u> Line Section <u>29</u> Township <u>14S</u> Range <u>34E</u> NMPM <u>Lee</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>10,500</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5-23-89 Started drilling out cement plugs at surface, 374', 1945' and 4450', circulated and cleaned out hole to 5498'.
- 6-7-89 Tie back 8 5/8" csg. from stub at 478' to surface, cemented with 250 sx Class "C" with 2% cacl. circulated 100 sx. to surface in pit.
- 6-12-89 Drill out cement and circulated hole down to 5498'. Prep to move in drilling rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frances Holzgraf TITLE Production Clerk DATE June 13, 1989

TYPE OR PRINT NAME Frances Holzgraf TELEPHONE NO. 915 683 5271

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 15 1989