

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
Name of Operator Mewbourne Oil Company		8. Farm or Lease Name Etcheverry "A"
Address of Operator P. O. Box 7698, Tyler, Texas 75711		9. Well No. 2
Location of Well UNIT LETTER <u>E</u> <u>2080</u> FEET FROM THE <u>North</u> LINE AND <u>560</u> FEET FROM THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>14S</u> RANGE <u>34E</u> N.M.P.M.		10. Field and Pool, or Wildcat Tres Papalotes Penn, West
15. Elevation (Show whether DF, RT, GR, etc.) 4139' GL		12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
 TEMPORARILY ABANDON ☐  
 PULL OR ALTER CASING ☐  
 OTHER ☐

PLUG AND ABANDON ☐  
 CHANGE PLANS ☐

REMEDIAL WORK ☐  
 COMMENCE DRILLING OPNS. ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER ☐

ALTERING CASING ☐  
 PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5/24/85 - Set CIBP at 10,355'. Dumped 4 sacks of cement with bailer.
- 8/20/85 - Circulated hole with 9.5#, 35 viscosity plug mud. Spotted 20 sack plug at 7990', 20 sack plug at 5922'.
- 8/21/85 - Took stretch on 4-1/2" casing. Free pointed at 5600'. Cut off casing at 5580'.
- 8/22/85 - Finished pulling 4-1/2" casing. Spotted 35 sack plug at 5580'.
- 8/23/85 - Tagged plug at 5535'. Spotted 35 sacks at 4450'. Tagged plug at 4280' with wireline. Spotted 35 sacks at 1945'.
- 8/24/85 - Welded on 8-5/8" casing. RU casing jacks. Free pointed and cut off at 487'.
- 8/27/85 - Spotted 90 sack cement plug. Pulled out of hole. WOC 4 hours. Rigged up wireline. Tagged plug at 374'. Rigged down wireline and set 10 sacks surface plug and erected dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Raymond Thompson

TITLE Exploration Secretary

DATE August 28, 1985

APPROVED BY Jack Griffin

TITLE OIL & GAS INSPECTOR

DATE OCT 22 1986

CONDITIONS OF APPROVAL, IF ANY: