

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24474

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No. V -1413

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

CITIES SERVICE STATE

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
M&W OF LOVINGTON, INC.

8. Well No. 1

3. Address of Operator
BOX 922, LOVINGTON, NM 88260

9. Pool name or Wildcat
HIGH PLAINS, PENN.

4. Well Location
Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line
Section 26 Township 14S Range 34E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Move in and rig up.
- 2) Set C.I.B.P. @ \pm 9600'. Cap w/ 35' cement.
- 3) Nipple up to 5-1/2" csg. Stretch, cut & pull casing.
- 4) Spot 50 sx cement 5-1/2" stub plug. 50' in & out of stub.
- 5) Spot 50 sx cement from 4594' - 4494'.
- 6) Nipple up to 8-5/8" casing. Stretch, cut & pull casing.
- 7) Spot 50 sx cement 8-5/8" stub plug. 50' in & out of stub.
- 8) Spot 50 sx cement 428' - 328'.
- 9) Spot 10 sx surface plug. Cut off wellhead. Erect dry hole marker.

** Circulated mud laden fluid between all plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

P&A AGENT

DATE 12/30/91

TYPE OR PRINT NAME

G.A. BABER

TELEPHONE NO. 392-5516

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 03 '92