

|                    |  |  |
|--------------------|--|--|
| OF COPIES RECEIVED |  |  |
| DISTRIBUTION       |  |  |
| FA RE              |  |  |
| E                  |  |  |
| G.S.               |  |  |
| ID OFFICE          |  |  |
| TRATOR             |  |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO ABANDON OR TO REOPEN OR RELOCATE TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - AN (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator  
**ELK OIL COMPANY**

Address of Operator  
**P. O. BOX 310, ROSWELL, NEW MEXICO 88201**

Location of Well  
UNIT LETTER **K** **1980** FEET FROM THE **South** LINE AND **1830** FEET FROM  
THE **West** LINE, SECTION **26** TOWNSHIP **14S** RANGE **34E** NMPH.

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
**K-3714**

7. Unit Agreement Name

6. Form of Lease Name  
**Cities Service State**

9. Well No.  
**2**

10. Field and Pool, or Wildcat  
**High Plains Penn**

12. County  
**Lea**

15. Elevation (Show whether DF, RT, GR, etc.)  
**4078 GL**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐

PERMANENTLY ABANDON ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

RELOCATE OR ALTER CASING ☐ CHANGE PLANS ☐ CASING TEST AND CEMENT JOBS ☐

OTHER ☐ OTHER ☐

SUBSEQUENT REPORT OF:

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Elk Oil Company proposes to Plug and Abandon well as follows:

1. 50' plug @ 10,445 perforation.
2. Attempt to recover 8,000' of pipe, 50 sx. plug in and out of 4 1/2" casing stub @ 8,000'.
3. 50' plug @ 6,000'.
4. 50 sx. plug @ base of 8 5/8" casing @ 4540'.
5. Attempt to pull 1500' of pipe, 100' plug inside and out of 8 5/8" casing stub @ 1500'.
6. 10' plug @ surface.
7. Standard 4' x 4' dry hole marker.
8. Mud between all plugs.

**100' PLUG ACROSS SHOULDER OF SURFACE PIPE**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by **Joseph J. Kelly** TITLE **President** DATE **3/20/86**

ORIGINAL SIGNED BY **JERRY SEXTON** DISTRICT I SUPERVISOR

DATE **MAR 24 1986**