

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
1-6933	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>Amini Oil Company</u>		8. Farm or Lease Name <u>Superior State</u>
3. Address of Operator <u>405 Wall Towers East - Midland, Tx. 79701</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>K</u> , <u>1873</u> FEET FROM THE <u>South</u> LINE AND <u>2086</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>14S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat <u>Undesignated</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4154.1 GR</u>		12. County <u>Lea</u>

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-24-74 Set cast iron bridge plug @10,530' w/35' cement cap on plug; set cast iron bridge plug @10,390' w/35' cement cap on plug.

6-7-74 Shot 5 1/2" csg. @7480', 6491' & 5789'. Couldn't pull csg. loose. Shot 5 1/2" csg. @5273'. Pulled 5273' of 5 1/2" csg. Spotted 50 sack plug @5223'-5323'. (5 1/2" stub). Spotted 50 sack plug @4080'-4180' (8-5/8" shoe).

6-8-74 Shot 8-5/8" csg. @2513' & 2007'. Couldn't pull loose. Shot csg. @1597'. Pulled 1597' of 8-5/8" csg.

6-11-74 Spotted 75 sack plug @8-5/8" stub. (1547'-1647').  
Spotted 75 sack plug @12-3/4" surface csg. shoe (265'-365').

6-12-74 Spotted 10 sack plug @ surface. Set surface marker & cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nathan E. O'Leary TITLE Agent DATE 8-1-74

APPROVED BY Nathan E. O'Leary TITLE Agent DATE 8-1-74

CONDITIONS OF APPROVAL, IF ANY: