

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS		8. Farm or Lease Name Stevens, 7501 JV-D Co
3. Address of Operator 104 South Pecos, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER "J" 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 12-S RANGE 33-E NMPM.		10. Field and Pool, or Wildcat North Bagley, Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4244 G. L.		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-29-75 Moved in Permian Basin Casing Pullers.

9-1-75 Layed down 283 Jts 2-3/8" tbg. Set 4sx cmt on top of CIBP @9,285'.
Set CIBP @8,400' w/5 sx cmt on top.

9-2-75 Shot 5-1/2" csg @6,928' & 6,633'.

9-3-75 Rec 210 Jts or 6,633' of 5-1/2" csg. Set 40 sx cmt @6,600'.
Set 40 sx cmt @5,140'. Set 40 sx cmt @3,800'.

9-4-75 Shot 8-5/8" csg @991'.

9-5-75 Recovered 25 Jts or 991' of 8-5/8" csg.
Set 60 sx cmt @991'. Set 65 sx cmt @425'.

9-6-75 Set 10 sx cmt @Surface.
Installed Dry hole marker. P&A 9-6-75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Bob Newland</u>	Bob Newland	TITLE <u>Regulatory Supervisor</u>	DATE <u>9-8-75</u>
		OIL & GAS INSPECTOR	
APPROVED BY <u>Eddie W. Seay</u>		TITLE _____	DATE <u>23 1978</u>
CONDITIONS OF APPROVAL, IF ANY:			