(May 1968) DEPA	H. FED STATES ARTMENT OF THE IN	TERIOR (Other instructions on verse side)	5. LEASE DESIGNATION	n No. 42-B142
	GEOLOGICAL SURVI		6. IF INDIAN, IALLOTTE	OR TRIBE NAME
SUNDRY I	NOTICES AND REPOR	RTS ON WELLS		
(Do not use this form for Use "Al	proposals to drill or to deepen or PPLICATION FOR PERMIT—" for	plug back to a different reservoir, such proposais.)	F 4 8 9	
ī			7. UNIT AURIEMENT NA	MB PHA DE
WELL GAS WELL OT	RER	DEPENDENT.		
2. NAME OF OPERATOR		摆模 点 医乳腺 医乳腺	8. FARM OR LHAME NAM	
Tom L. Ingram		111	Trinity 3	
3. ADDRESS OF OPERATOR	Now Marico 88201		#1 2 3 3	
POB 1757, Roswell, New Mexico 88201 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, O	WILM AT
See also space 17 below.) At surface		Wildcani 🖫		
		科以 公司。	11. SEC., T., H., M., OR SURVEYTOR AREA	LK. AMD
766' FSL & 554 FV	VL of Section		5 0 0 A	
			Sec. 328, TI	25, R3BE
14. PERMIT NO.	15. BLEVATIONS (Show wh	ether DF, RT, GR, etc.)	, as # E	MA
	3827 GR		Lea S	1 To a Nin
16. Che	ck Appropriate Box To Indi	cate Nature of Notice, Report,	or Other Data # # # # #	[] [] () () () () () () () () () (
Notice of	F INTENTION TO:	su	BEQUENT REPORT OF	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	E BETARRING	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	a salatening c	BING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	a	m •
REPAIR WELL	CHANGE PLANS		esults of multiple dompfetion	on Wedl
(Other)		Completion or Report reportinent details, and give pertinent	completion Report and Log for	Im.
Plan to set 1001	plug @ 12,200-12,30	ll stem tested the Dev O. Set 100' plug @ ll th 350 sks. Approval	JOG. No. 1870. Mr	gi Cl
18. I hereby certify that the fore	gologis frue and correct	OPERATOR	BAND 5/	9/75 : 1 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
(This space for Federal or S	tat office use)		a 2 S D MIC	Total
APPROVED BY	TITI	æ	BATE :	<u> </u>
CONDITIONS OF APPROVA	L, IF ANY:		MĀŸ 1 3 18	75 E R F