

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
1286-N	
7. Unit Agreement Name	
8. Farm or Lease Name	
State "35"	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Tul/K/Pennsylvanian	
12. County	
Lea	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator	
Saxon Oil Company	
3. Address of Operator	
P. O. Box 2948, Midland, Texas 79701	
4. Location of Well	
UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM	
THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>14-S</u> RANGE <u>32-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4284' GL	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Load hole w/mud laden fluid.
Set 5-1/2" CIBP @ 9700', Cap w/35' cement.
Cut 5-1/2" csg. @ 8,000' and pull csg.
Run tubg. to 8050', spot 40 sx. cement.
Spot 40 sx. cement @ 7658' (Abo).
Spot 40 sx. cement @ 4135' to cover bottom 8-5/8" csg. & (San Andres).
Spot 40 sx. cement @ 1700' (Salt).
Cut 8-5/8" csg. @ 800'.
Spot 80 sx. cement @ 850'.
Spot 100 sx. cement @ 450' (In & Out of Surface).
Spot 10 sx. cement @ surface.
Weld on plate and marker.
Clean location.

THE COMMISSION HAS BEEN NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE ABOVE WELL.

100' PLUG AT TOP OF GULFSTREAM

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Superintendent DATE 1/5/76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 7 1976