

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Lowe	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat, Undesignated	
12. County	
Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **P & A**

2. Name of Operator  
**Roger C. Hanks**

3. Address of Operator  
**500 Gihls Tower West, Midland, Texas 79701**

4. Location of Well  
UNIT LETTER **M** **660** FEET FROM THE **West** LINE AND **660** FEET FROM  
THE **South** LINE, SECTION **4** TOWNSHIP **14S** RANGE **37E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3867' GR**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒  
OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1 - Spud well 12-29-75
- 2 - Set 13-3/8" casing at 400' on 12-30-75. Circ Cement
- 3 - Set 9-5/8" casing at 4732' on 1-9-76. Cemented with 325 sacks
- 4 - Drilled to total depth of 11,632'
- 5 - Logged and Plugged well as follows:
  - a - 35 sacks - 11,500-11,632'
  - b - 40 sacks - 10,145-10,300'
  - c - 30 sacks - 9693-9808'
  - d - 40 sacks - 8185-8340'
  - e - 40 sacks - 6130-6285'
  - f - 75 sacks - 4430-4770'
- 6 - Will cut and pull 9-5/8" casing and finish P & A as follows
  - a - 100' in stub.
  - b - 100' at base of salt if exposed
  - c - 100' at Top of salt if exposed
  - d - 100' in and out of 13-3/8"
  - e - 10 sacks at Top.
  - f - Install DHM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *JB Shepherd* TITLE Operations Manager DATE March 5, 1976

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE M

CONDITIONS OF APPROVAL, IF ANY: