

Submit 3 Copies
to Appropriate
District Office

STATE OF NEW MEXICO
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1900, Hobbs, NM 88240

DISTRICT II
P.O. Drawing DD, Artesia, NM 88210

DISTRICT III
1000 E. Benson Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25363
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-8879

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Anderson State
2. Name of Operator Elk Oil Company	8. Well No. 1
3. Address of Operator P.O. Box 310 Roswell, NM 88202	9. Pool name or Wildcat High Plains Permo Penn
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>14 South</u> Range <u>34 East</u> <u>NMPM</u> <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4075' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-06-93 Set CIBP @ 10,400' - 15 sxs on top - 10,200'.
11-08-93 Spot 30 sxs @ 9816' - 9700'.
11-08-93 Spot 30 sxs @ 6070' - 5900'.
11-09-93 Spot 55 sxs @ 4632' - tag @ 4497' - pulled 4582' of 5 1/2".
11-10-93 Spot 25 sxs @ 4497' - 4400'.
11-10-93 Spot 35 sxs @ 2200' - 2100'.
11-10-93 Spot 35 sxs @ 425' - 325'.
11-10-93 Spot 10 sxs @ 30' - surface.

Install dry hole marker
Circulate with mud
Ready for Inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly TITLE President DATE 7/16/96
TELEPHONE NO. (505)623-3190

(This space for State Use)

APPROVED BY Termy M. Hill TITLE OIL & GAS DIRECTOR DATE SEP 11 1996

CONDITIONS OF APPROVAL, IF ANY