

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

50. Indicate Type of Lease
State ☐ Fee ☒ XX
51. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gil-Mc Oil Corporation	8. Farm or Lease Name Long
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER C 900 FEET FROM THE North LINE AND 2200 FEET FROM THE West LINE, SECTION 8 TOWNSHIP 14S RANGE 37E NMPM.	10. Field and Pool, or Willacot West King Penn
11. Elevation (Show whether DF, RT, GR, etc.) 3877 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged for abandonment as follows:

Circulated hole with mud.
Shot & pulled 5 1/2" casing from 5165.
Ran 2 3/8" tubing to 5195 and spotted 100 sack plug in and out of 5 1/2" casing stub.
WOC 24 hours, tagged top of plug at 4906.
Re-filled hole with mud.
Spot 50 sack plug across 8 5/8" casing shoe at 4739.
Tag top of plug at 3612.
Spot 30 sack plug at 2550.
Set 10 sack plug at surface with regulation marker.
Work complete 5/17/80.
The Commission will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Hanna Walker TITLE Agent DATE 5/21/80

APPROVED BY M. J. Patterson TITLE OIL & GAS INSPECTOR DATE 5/21/80

CONDITIONS OF APPROVAL, IF ANY: