

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.O.S. | |
| LAND OFFICE | |
| OPERATOR | |

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" - FORM C-101 FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Gil-Mc Oil Corporation | 8. Farm or Lease Name Long |
| 3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER C , 900 FEET FROM THE North LINE AND 2200 FEET FROM THE West LINE, SECTION 8 TOWNSHIP 14S RANGE 37E NMPM. | 10. Field and Pool, or Wildcat West King Penn |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3877 GR | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Started running 2 7/8" tubing to convert to water disposal well.
Dropped 6840' tubing, recovered 8 joints, unable to recover remainder.
Found casing collapsed at 5200'. Preparing to plug as follows:

Cut & pull casing from 5100'
Spot 100 sack plug across casing stub
Spot 50 sack plug across 9 5/8" casing shoe at 4739
Spot 50 sack plug across top of salt at 2550
Mud between all plugs
Location to be cleared & leveled

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Harry Sexton* TITLE Agent DATE 5/7/80

APPROVED BY Harry Sexton TITLE Dist. 1 Super. DATE MAY 8 1980

CONDITIONS OF APPROVAL, IF ANY: