

1. Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26442
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Barbee LL
8. Well No. 1
9. Pool name or Wildcat Austin Mississippi
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975.8' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>18</u> Township <u>14S</u> Range <u>36E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975.8' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Repair tubing/casing leaks <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-6-95 - Moved in and rigged up pulling unit. Bled pressure off well. TIH with gauge ring, chisel and bailer. Could not get past 10980' with any wireline tools. Retrieved small pieces of rock in bailer. Cut bolts and nuts off wellhead. Pulled 72000# to unflange wellhead. Nippled down wellhead and installed BOP. Shut down.

9-6-95 - Worked tubing. Could not get off on/off tool or unset packer. Shut down to discuss options.

9-9-11-95 - Rigged up wireline. TIH with free point tools. Free point 2-3/8" tubing as follows: 10348' (100% free); 10355' (100% free); 10360' (30% free); 10375' (20% free) and 10387' (1% free). TOOH with free point tools. TIH with chemical cutters. Cut 2-3/8" tubing off at 10000'. TOOH with cutters and rigged down wireline. TOOH and lay down 2-3/8" tubing.

9-12-95 - Rigged up wireline. TIH with gauge ring to 9950'. TOOH with gauge ring. TIH with logging tools and ran pipe inspection log. TOOH with logging tools. Start in hole with RBP, packer and new 2-3/8" tubing. Shut down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 9-29-95

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Gerry Sexto TITLE DISTRICT I SUPERVISOR DATE OCT 10 1995

CONDITIONS OF APPROVAL, IF ANY: