' Submit 3 Copies to Appropriate District Office	Energe Ainerals and Natural Resources Department		Form C-143 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-26442		
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM \$7410			6. State Oil & Gas Lesse No.	
SUNDRY NOTICES AND REPORTS ON WELLS				
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OL OAS WELL WELL X OTHER			Barbee LL	
			8. Well No. 1	
			9. Pool name or Wildcat	
105 South 4th St., Artesia, NM 88210			Austin Mississippi	
4. Weil Location Unit Letter <u>G</u> : 1980 Feet From The North Line and 1980 Feet From The East Line				
Section 18 Township 14S Range 36E NMPM Lea County				
3975.8' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				
PULL OR ALTER CASING CASING TEST AND C				
OTHER:	THER: OTHER:Repair		tubing/casing leaks	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
9-19-95 - TOOH with tubing, drill collars and bit. TIH with retrieving tool and 2-3/8" tubing. Reversed sand off of RBP at 9980'. Unset RBP and TOOH with tubing and RBP. TIH with sealed lead tubing patch and 2-3/8" tubing to tubing at 10000'. Reversed annulus with 110 bbls 2% KCL water with corrosion inhibitor. Latched onto tubing at 10000'. Removed BOP and nippled up wellhead. Pressured annulus to 400 psi to test				
tubing tie-in - no leaks. Shut down.				
9-20-95 - Rigged up coiled tubing unit. 9-21-95 - TIH with hydrohammer on 1-1/4" coiled tubing. Tag plug at 10993'. Pumped N2				
foam and worked hydrohammer. Made 2' in 2-1/2 hours. TOOH with coiled tubing and hydro-				
hammer. TIH with hydrojet and 1-14/" coiled tubing. Tag plug at 10995'. Pumped N2 foam				
and worked hydrojet thru bridges to Vann guns at 13357'. Blow tubing dry with N2. TOOH with coiled tubing and hydrojet. Opened well to flow N2 from well. Shut in.				
	9-22-95 - Flare well to pit. Shut in overnight.			
9-23-25-95 - Flare w	ell to pit. Made swab i	cun. Shut well	in. Released to production.	
I hereby certify that the information above in	true and complete to the best of my knowledge and			
SKONATURE	flis T	ne Production	Clerk DATE9-29-95	
TYPE OR FRANT MAME RUSty Kle	in		<u>телетнома но. 505/748-1471</u>	
(This space for State Use) ORIGINAL S	IGNED BY JERRY SEXTON		. •	
	RICT I SUPERVISOR		OCT 1 0 1995	
	π	ī.e	DATE	
CONDITIONS OF APPROVAL, IF ANY:				

.