

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5919
7. Unit Agreement Name
8. Farm or Lease Name Lea State
9. Well No. 1
10. Field and Pool, or Wildcat Baum Penn (Bough C)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Southland Royalty Company
3. Address of Operator 1100 Wall Towers West, Midland, TX 79701
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 13S RANGE 32E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 4312' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-12-82 Spotted 15 sxs cmt 50' to surface. Cmt off wellhead. Welded on plate and installed dry hole marker. P&A complete 1-12-82. Procedure previously approved August, 1981 per Jerry Sexton.

1. Set CIBP @ 9400' and spotted 50' cmt plug (15 sxs) on top of it.
2. Ran in hole w/perforating gun to shoot csg. off.
3. Pulled 8000' of 5 1/2" csg from well.
4. Spotted 200' of cmt (60 sxs) from 4617-4466'.
5. Spotted 200' of cmt (60 sxs) across 8 5/8" csg. shoe.
6. Spotted 100' of cmt (60 sxs) from 1747-1540'.
7. Spotted 40 sxs cmt from 410-203'.
8. Spotted a 50' cmt plug (15 sxs) from surface to 50'.
9. Install marker on well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *David Cutanash*

TITLE Dist. Production Manager

DATE 1-12-82

APPROVED BY *David Cutanash*
CONDITIONS OF APPROVAL, IF ANY:

TITLE OIL & GAS INSPECTOR

DATE AUG 19 1983