41 (42)69 *******		
DISTRIBUTION		
SANTA PE		
rice		
U.S.G.S.		-
LAND OFFICE		
	T	

CONDITIONS OF APPROVAL, IF ANYS

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

Revised 10-1-7 SANTA FE, NEW MEXICO 87501 Sa. Indicate Type of Leise State X 5. State Oil & Gas Lease No. LG-3334 SUNDRY NOTICES AND REPORTS ON WELLS 7. Unit Agreement Name ١. 2. Name of Operator 8. Farm or Lease Name Harvey E. Yates Company Superior 19 State 3. Address of Operator 9. Well No. P. O. Box 1933, Roswell, New Mexico 88201 1 4. Location of Well 10. Field and Pool, or Wildcat . 1980 North 660 Austin-Mississippian 19 14S East 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3670' GR Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDONMEN CASING TEST AND CEMENT JOB Cement plugs & Directional Drilling 17. Describe Proposed or Completed Operations (Cleurly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 8/08/80 Depth-10,249' ----- on trip out to PU Dyna Drill. Dressed plug to 10,249'; drld 30' of cement in 1 hr from 10,219' to 10,249'. Totco: 2 1/4° North 32 East @ 10,210'. Depth 10,249' on trip out w/Dyna Drill. Formation - lime and shale; 10' of 8/09/80 progress. 1 hr-PU Dynda Drill; 1 hr-pulling out wire. 8/10/80 Depth-10,300. Circulating to set cement plug. Formation - lime, shale and cement. Plug #3; 200 sxs Class "H", 5% CFR-2. 8# sand/sx @ 18#/gal.PD @ 8:15 a.m. 8/10/80. 8/11/80 Depth-10,300' WOC. 1/4 hr-service rig; 2 hrs-circulating; 2 hr-cementing plug w/200 sx; 20 3/4 hrs-WOC. 8/12/80 Depth- 10,941'; stuck. 8/13/80 Depth-11,121' on trip out w/fish. 5 1/2 hrs-working stuck DCs; 5 1/4 hrs-running free point; backed off @ 10,836' leaving 4 DCs in hole; 2 1/2 hrs-jarring on fish. SEE ATTACHMENT FOR CONTINUATION: 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 9/15/80 \* exterio