

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER: Plug & Abandon
Name of Operator Yates Petroleum Corporation		
Address of Operator 207 South 4th St., Artesia, NM 88210		
Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>20</u> TOWNSHIP <u>14S</u> RANGE <u>36E</u> NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name Head State
9. Well No. 1
10. Field and Pool, or Wildcat Austin-Mississippian
12. County Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3954' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well as follows:

1-9-81 Cut casing off at 11190'. Pulled approximately 1/2 of casing from well.

Plugs set as follows:

Plug #1 - 11230-11130' w/35 sacks Class "C"
Plug #2 - 9825-9725' w/35 sacks Class "C"
Plug #3 - 8200-8100' w/35 sacks Class "C"
Plug #4 - 5800-5700' w/35 sacks Class "C"
Plug #5 - 4700-4600' w/35 sacks Class "C"
Plug #6 - 2100-2000' w/25 sacks Class "C"
Plug #7 - 10-surface w/5 sacks Class "C"

Heavy mud placed between plugs. Installed dry hole marker.

Verbal approval for plugging procedure obtained from Mr. Jerry Sexton, OCD, Hobbs, 1-7-81.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Juanita Doodett</u>	TITLE <u>Production Supervisor</u>	DATE <u>8-16-83</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>OCT 2 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
AUG 18 1983
O.C.D.
HOBBS OFFICE