

XII.

We have examined available geological and engineering data and found no evidence of open faults or any other hydrologic connections between the disposal zone and any underground source of drinking water. (See attached Geo-Map contour maps).