

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-124	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator MWJ PRODUCING COMPANY		8. Farm or Lease Name Baum 17 State
3. Address of Operator 1804 First National Bank Bldg Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM West 17 14S 33E THE LINE, SECTION TOWNSHIP RANGE NMPM.		10. Field and Pool, or Wildcat Baum Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4247' gGL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/16/86: Removed W/H assy & pulled 1" vent string. Pulled & LD pump cavity, pkr, 317 jts 2-3/8" tbg & 3 jts T/P. RU CRC. Ran & set CIBP @ 9800' w/35' cmt.  
12/17/86: Ran perf sub & 294 jts 2-3/8" tbg & w/end of tbg flange @ 9100', put on flange.  
12/18/86: MI & RU csg pullers.  
12/19/86: Loaded hole w/10# mud. Spt'd 25 sc cmt plug @ 9100'. Pulled & LD 116 jts tbg. Spt'd 25 sx cmt plug @ 5500. Pulled & LD 44 jts tbg. Pulled & stood up 134 jts tbg. Removed tbg head & shot csg off @ 4173'. Pulled & LD 2 jts 5-1/2" csg.  
12/20/86: Pulled 105 jts 5-1/2" csg. Ran 135 jts 2-3/8" tbg & spt'd 75 sx cmt plug @ 4180'. Pulled 48 jts tbg.  
12/23/86: Ran 40 jts tbg & tagged plug @ 3930'. Pulled & LD 80 jts tbg & spt'd 35 sx cmt plug @ 1705' w/10# mud. Pulled & LD 55 jts tbg. Cut off Csg head. Spt'd 10 sx cmt plug from 25' to surface. Installed dy hole marker. Well P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Drexler TITLE Pat Drexler - Agent DATE 12/30/86

APPROVED BY Lytle F. Turnerscliff TITLE DEPT GAS INSPECTOR DATE OCT 28 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
DEC 31 1986  
OCD  
MOBBS OFFICE