

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
Harvey E. Yates Company
Address of Operator
P. O. Box 1933, Roswell, New Mexico 88201
Location of Well
UNIT LETTER P 660 FEET FROM THE South LINE AND 990 FEET FROM
THE East LINE, SECTION 33 TOWNSHIP 13S RANGE 36E

7. Unit Agreement Name
McDonald Unit
8. Farm or Lease Name
9. Well No.
1
10. Field and Pool, or Wildcat
Wildcat-Penn
11. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)

3866.4

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐
OTHER Plug Back & Test ☐			

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROCEDURE:

- GIH w/5 1/2" CIBP & set @ 10,700' & dump 35' cmt on top. POH.
- GIH w/4" csg gun & perf 1 JS @ 10,520', 10,420.5, 10,521, 10,521.5, 10,522, 10,522.5, 10,523, 10,523.5, & 10,524' (9 holes). POH
- GIH w/5 1/2" Model R Pkr, SN & 2 3/8" tbg & spot 200 gals 15% MSR-100 w/cationic surfactants & phosphates. PU & set pkr above perfs, reverse acid into tbg & break down perfs (Dolomite Lithology).
- If non-commercial, POH & GIH w/5 1/2" CIBP & set above perfs w/10-15' cement on top. POH.
- GIH w/4" csg gun & perforate 1JS @ 10,252, 10,252.5, 10,253, 10,253.5, 10,254, 10,254.5, & 10,255' (7 holes), POH, (Limestone Lithology).
- GIH w/5 1/2" Model R pkr, SN & 2 3/8" tbg & spot 150 gals 15% MSR-100 w/cationic surfactants & phosphates over perfs. Pull pkr above perfs & reverse acid into tbg. Break down perfs.
- Run rods & pump. Set up artificial lift equipment & turn over to pumper.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

WELL NO. 412 TITLE V. P. of Operations DATE 12/4/84

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

RECORD ONLY

RECEIVED

DEC 12 1984

U.S. DEPT.
OF JUSTICE