

DISTRIBUTION		
DATE		
BY		
TO		
FROM OFFICE		
BY		

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes Old
C-102 and C-101
Effective 1-4-88

6. Indicate Type of Lease	
State ☒	Free ☐
7. State Oil & Gas Lease No.	
K-6602-2	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG OPEN TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒	GAS WELL ☐	OTHER ☐
Name of Operator		
Coastal Oil & Gas Corporation		
Address of Operator		
P. O. Box 235, Midland, Texas 79702		
Location of Well		
UNIT LETTER A -660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 14-S RANGE 32-E N.M.P.V.		

7. Unit Agreement Name
8. Farm or Lease Name
State "1"
9. Well No.
2
10. Field and Pool, or Allotment
Baum (U. Penn)
11. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)

4288.8 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☒
LL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

- 6-22 POOH with tubing & rods.
- 6-23 Set CIBP @ 9435'. GIH w/tbg, started circulating hole with mud and lost pressure. GIH to tag plug, plug had fallen downhole. POOH with tbg. RU WL, set CIBP @ 9372'. GIH w/dump bailer and dump 35' of cmt on CIBP. GIH with tbg to 8638', circ hole with mud. SDFN.
- 6-24 Start OOH with tbg, tbg dry. RIH w/WL & tag plug at 9368'. POOH w/tbg. Dump 8 sacks sand down casing. SD for weekend.
- 6-27 GIH w/packer on tbg. Tag plug, PU 20' & set pkr. Load tbg & test plug to 500 psi @ surface, OK. PU & set pkr at 8733' & test plug to 1000#, OK. GIH w/dump bailer, dump 35' cmt on CIBP.
- 6-28 Cut 5 1/2" casing at 7005', pulled 180 jts 5 1/2" casing. TIH w/tbg to 7060'. Circ thru hole with mud and spot 50 sack plug. POOH with 35 stands, WOC. GIH & tag plug at 6960'. PU to 4162', spot 50 sack plug. SDFN.
- 6-30 GIH w/tbg & tag plug at 4059'. PU to 1665', spot 35 sack plug. LD tbg, cut off wellhead, installed P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY B. L. Smith TITLE Petroleum Engineer DATE 7-29-88

PROVED BY David R. Smith TITLE OIL & GAS INSPECTOR DATE 04 1988