

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br><b>30-025-27579</b>   |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br><b>LG-3487</b>  |
| 7. Lease Name or Unit Agreement Name:<br><b>North Baum</b>  |
| 8. Well No.<br><b>2</b>   |
| 9. Pool name or Wildcat<br><b>Baum Upper Penn</b>   |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
**Read & Stevens, Inc.**

3. Address of Operator  
**P. O. Box 1518 Roswell, NM 88202**

4. Well Location  
Unit Letter **A** : **660** feet from the **North** line and **660** feet from the **East** line  
Section **24** Township **13S** Range **32E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**4,298' GL**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

08/14/02 Set circ @ 9,143', squeeze 50 sx below, spot 15 sx to 8,925'.  
08/16/02 Spot 25 sx @ 7,600'-7,400'.  
08/19/02 Perforated @ 5,400', could not pump into perms.  
08/19/02 Spot 25 sx @ 5,450'-5,203' tagged.  
08/20/02 Pulled 4,060' of 5 1/2" csg.  
08/20/02 Spot 50 sx @ 4,110'-3,946' tagged.  
08/21/02 Spot 30 sx @ 1,700'-1,600' tagged.  
08/21/02 Spot 35 sx @ 465'-339' tagged.  
08/21/02 Spot 15 sx @ 60' to surface.  
Install dry hole marker.  
Circulate 10# mud.  
Move in & rip location. Reseed with native grasses.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Maxey, Jr. TITLE **Operations Manager** DATE **10/11/02**

Type or print name **John C. Maxey, Jr.** Telephone No. **505/622-3770**

(This space for State use)

APPROVED BY GARY W. WINK TITLE

Conditions of approval, if any: **OC FIELD REPRESENTATIVE II/STAFF MANAGER**

GWW

JAN 15 2003