

NAME	DATE	TIME	LOCATION
JOHN DOE	10/10/1964	10:00	100-44-38861
JANE DOE	10/10/1964	10:00	100-44-38861
JOHN DOE	10/10/1964	10:00	100-44-38861
JANE DOE	10/10/1964	10:00	100-44-38861
JOHN DOE	10/10/1964	10:00	100-44-38861
JANE DOE	10/10/1964	10:00	100-44-38861
JOHN DOE	10/10/1964	10:00	100-44-38861
JANE DOE	10/10/1964	10:00	100-44-38861
JOHN DOE	10/10/1964	10:00	100-44-38861
JANE DOE	10/10/1964	10:00	100-44-38861

OF CONSERVATION DIVISION

SANTA FE, N.M. 87501 37501

Form 6-73
Revised 10-1-73

DATE YEAR ☒

Richardson Unit

Undes. Austin - Miss

Harvey E. Yates Company

P. O. Box 1933, Roswell, New Mexico 88201

660

North

1980

West

5

14S

36E

3968.0'

Lea

Production Casing String

12/30/81 Day 54, Operation - ND, Depth - 13,393' TD. CIrc 8 hrs, Run 5 1/2" Csg
9 3/4 hrs, cmtg 2 1/4 hrs, ND 4 hrs. Ran:

66 jts - 5 1/2"	20#	N-80 LT&C	2822.50'
201 jts - 5 1/2"	17#	N-80 LT&C	8304.87'
1 jt - 5 1/2"	17#	N-80 LT&C Butt	32.40'
<u>54</u> jts - 5 1/2"	17#	N-80 Buttress	<u>2234.07'</u>
		Total	13,400.34'

Set @ 13,393'. Csg shoe @ 13,393'; FC @ 13,350'; DV stage collar @ 12,327
Cmtd w/1st stage 400 sx Class "H" plus .75% Halad 22-A, .5% CFR-2, 6#/sk salt
& 1/4# sk flocele. Plug down @ 4:30 p.m., 12/29/81. Circ 6 hrs, circ 25
sx fr 1st stage. 2nd stage 800 sx Class "H" plus .75% Halad 22-A, .5%
CFR-2, 6#/sk salt, 1/4#/sk flocele. Plug down @ 11:45 p.m., 12/29/81.
WOC 6 hrs, set slips. String wt 190,000#, set 170,000# on slips. WOCU.
Dropped from report pending completion.

Engineer

DATE 1-7-82

Orig. Signed by
Jerry Brown
Dist 1, Senate