District 1 PO Box 1980, Hobbs, NM 88241-1980 District II PO Drawer DD, Artesia, NM 88211-0719 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV PO Box 2088, Santa Fe, NM 87504-2088

01-09-95

(915) 684-7441

### State of New Mexico Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088 Form C-101 Revised February 10, 1994 Instructions on back Submit to Appropriate District Office State Lease - 6 Copies Fee Lease - 5 Copies

# AMENDED REPORT

# APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

							······						
<sup>1</sup> Operator Name and Address. MARALO, INC.										<sup>1</sup> OGRID Number 014007			
P. 0. BOX 832										<sup>3</sup> API Number			
MIDLAND, TX 79702											30 - 0 <b>25-27631</b>		
* Prope	rty Code				' Pi	roperty Name					* Weil Na.		
006354 SAMANTHA						STATE				1			
<sup>7</sup> Surface Location													
UL or lot no.	Section	Towaship	Range	Lot Ida	Feet from the	North/South En	oct from the	East/Wes	t line	County			
Р	7	14S	33E		660	SOUTH		660		Γ	LEA		
		<sup>8</sup> Pr	oposed	Bottom	Hole Locati	ion If Differ	rent I	From Sur	face				
UL or lot no.	Section	Township	Range	Lot Ida	Feet from the	North/South Ha	_	et from the	East/West line		Coeaty		
		' Propos	ed Pool I	<u>I</u>	1	L		" Propos	ed Pool 2		1		
" Work T	ype Code		Well Typ	e Code	<sup>13</sup> Cabie/	Rotary	14	Lease Type Co	de	<sup>14</sup> Ground Level Elevation			
P O			0		. R	R		S		4258 '			
<sup>14</sup> Multiple <sup>17</sup> Propos			Proposed	Depth	" For	stica		" Costractor		<sup>30</sup> Spud Date			
NO 9855'				' PBTD	WOLFC	CAMP UNK							
			21	Propose	d Casing ar	nd Cement I	Progr						
Hole Siz	be [	Casin	g Size		e weight/foot	Setting Dept	Sacks of Cement			Estimated TOC			
17 <b>5</b> "		13 3/8	•	48#		431'		400 SXS		SURF			
125		8-5/8"		28#		4100'		2700 SXS		SURF			
7-7,	7-7/8"		5-1/2"		•	10140'		1828 SXS/2 STAG		GES CIRC			
								DA LOOF 6 8388		•			
										1			
<sup>11</sup> Describe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary.													
SEE J	ATTACHED	SHEET											
13 Thanks and					12								
<sup>13</sup> I hereby certify that the information given above is true and complete to the best of my knowledge and belief.						OIL CONSERVATION DIVISION							
Signature:	noth	in 7	^p	Approved DORIGINGL SIGNED BY JERRY SEXTON									
Printed name:	EA LOGAN		Tit	Tide: DISTRICT I SUPERVISOR									
Tide:	TORY ANAL	YST	Ap	Approval Date: JAN 11 1995 Expiration Date:									
Date: Phone:						Conditions of Approval :							

Attached 🛛

#### C-101 Instructions

Measurements and dimensions are to be in feet/inches. Well locations will refer to the New Mexico Principal Meridian.

IF	THIS	IS	AN	AME	NDEC	) A	EPOF	RT	CHEC	ĸ	THE	80X	LABLED
- A	MEND	ED	REP	ORT"	AT T	ΉE	TOP	OF	THIS	DO	CUN	IENT.	

- Operator's OGRID number. If you do not have one it will be assigned and filled in by the District office.
- 2 Operator's name and address
- 3 API number of this well. If this is a new drill the OCD will assign the number and fill this in.
- 4 Property code. If this is a new property the OCD will assign the number and fill it in.
- 5 Property name that used to be called 'well name'
- 6 The number of this well on the property.
- 7 The surveyed location of this well New Mexico Principal Meridian NOTE: If the United States government survey designates a Lot Number for this location use that number in the 'UL or lot no.' box. Otherwise use the OCD Unit '.etter.
- 8 The proposed bottom hole location of this well at TD

9 and 10 The proposed pool(s) to which this well is beeing drilled.

- 11 Work type code from the following table:
  - N New well
  - E Re-entry
  - D Drill deeper
  - P Plugback
  - A Add a zone
- 12 Well type code from the following table:
  - O Single oil completion
  - G Single gas completion
  - M Mutiple completion
  - I Injection well
  - S SWD well
  - W Water supply well
  - C Carbon dioxide well
- 13 Cable or rotary drilling code
  - C Propose to cable tool drill
  - R Propose to rotary drill
- 14 Lease type code from the following table:
  - F Federal
  - S State
  - P Private
  - N Navajo
  - J Jicarilla
  - U Ute
  - 1 Other Indian tribe
- 15 Ground level elevation above sea level
- 16 Intend to mutiple complete? Yes or No
- 17 Proposed total depth of this well

- 18 Geologic formation at TD
- 19 Name of the intended drilling company if known.
- 20 Anticipated spud date.
- 21 Proposed hole size ID inches, proposed casing OD inches, casing weight in pounds per foot, setting depth of the casing or depth and top of liner, proposed cementing volume, and estimated top of cement
- 22 Brief description of the proposed drilling program and BOP program. Attach additional sheets if necessary.
- 23 The signature, printed name, and title of the person authorized to make this report. The date this report was signed and the telephone number to call for questions about this report.

## WORKOVER PROGNOSIS

٤.

### MARALO INC

Samantha State "7" #1 660' FSL & 660' FEL, Sec 7, T-14-S, R-33-E Baum Field, Lea County, New Mexico

ELEVATIONS:	4258' GL	4272' KB (14' AGL)	9855' PBTD						
CASING: CURRENT	13 3/8" 8 5/8" 5 1/2" 17#	<ul> <li>@ 431' w/ 400 sx, circ'd to surface</li> <li>@ 4,100' w/2700 sx, circ'd to surface</li> <li>@ 10,140' w/1828 sx in 2 stages, DV @ 898</li> </ul>	38', circ'd						
PERFORATIONS:	9903 - 9950',  plugged w/CIBP + 35' cmt @ 9890' 9819 - 9845',  open								

PROPOSED OPERATION:

Test Wolfcamp pay

- 1. RUPU. TOH w/rods, pump & tbg.
- 2. RU wireline. TIH & set CIBP @ +/- 9800'. Cap w/35' cmt.
- 3. TIH w/tbg, open-ended, to 9461'. Spot 200 gals 15% NEFE, triple-inhibited, acid. TOH w/tbg.
- 4. RU perforators and TIH w/4" carrier guns loaded w/premium charges and shoot 2 JSPF @ 9434 9437' and 9451 9461' (total 28 holes). RD wireline.
- 5. TIH w/ 5 1/2" treating pkr on tbg to +/- 9350'. Reverse spot acid into tbg. Set pkr.
- 6. Breakdown perfs by pumping away spot acid.
- Continue treatment by pumping 2000 gals 15% NEFE carrying +/- 56 ball sealers down tbg at a rate of +/- 3 BPM. If ballout occurs, surge off balls and finish treatment.
- 8. Swab and evaluate.
- 9. TOH w/lbg & pkr. Run production equipment and place well on production.

<u>ک</u>



JAN 1 0 1835

O O O MARCO SOFFICE