Enc. Minerals and Natural Resources Department OIL CONSERVATION DIVISION WELL API NO. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-27724 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE L STATE DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 6. State Oil & Gas Lease No. FINE AND A K-4177 **ESUNDRY NOTICES AND REPORTS ON WELLS** DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Baum 8 State (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:
OH. A. WELL . 2 Name of Operator MWJ Producing Company 8. Well No. 3. Address of Operator 9. Pool name or Wildcat c/o P.O. BOX 10019 Midland, Texas 79702 Baum Upper Penn 4. Well Location Unit Letter J: 1980 Feet From The South Line and 1980 Feet From The East Line **₩**\$.8°... 14 S 33 E **NMPM** Township Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: [23] Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRU 10-20-90 Plug # 1 5-1/2" CIBP @ 9,500' w/35' Cement Plug # 2 90 SXS 5560-5340 Tag Stub 5-1/2 @ 5505' Plug # 3 50 SXS 4157-3999' Tag Plug # 4 40 SXS 1700-1560 Plug # 5 40 SXS 422-282 Plug # 6 10 SXS Surf. 25' Plugged to abandon 10/26/90 Install dry hole marker. mud between all plugs e is true and complete to the best of my knowledge and belief. Joey Fields mu Agent OCT 0 8 1998 OR & OAS MERSCIOR

DITIONS OF APPROVAL, F ANY:

RECEIVED

NOV 1 3 19**90** 

CO HOBS OME