

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil &amp; Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Kimbark Oil & Gas Company 12672	8. Farm or Lease Name M. F. Walker 18549
3. Address of Operator 511 West Ohio, Suite 131, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER 0, 1980 FEET FROM THE East LINE AND 660 FEET FROM South LINE, SECTION 27 TOWNSHIP 12-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat S.W. Gladiola Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3891.7	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
 TEMPORARILY ABANDON ☐  
 PULL OR ALTER CASING ☐  
 OTHER ☐

PLUG AND ABANDON ☐  
 CHANGE PLANS ☐  
 OTHER ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
 COMMENCE DRILLING OPNS. ☐  
 CASING TEST AND CEMENT JOBS ☐  
 OTHER ☐

ALTERING CASING ☐  
 PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following operations have been completed on the subject well.

- 2/3/86 - Mixed salt gell mud - circulated hole with mud and 10# brine.  
 2/4/86 - Set Bell CIBP @ 12,200' with wireline. Pumped 3 sks of cement on top of plug. Attempted to cut 5-1/2" csg. @ 5400' and 5000' but pipe not free. Cut pipe @ 4525' and pipe was free.  
 2/5/86 - Pulled 4525' of 5-1/2" pipe out of the hole. Set 35 sks of class C cement @ 7900'. Set 35 sks of C @ 5400'. Set 70 sks of C @ 4557'. SI.  
 2/6/86 - Tripped back into hole and tagged plug @ 4370'. Set 70 sks of class C cement @ 1500'. Set surface plug. Weld on plate and marker.

SET PLUGS AS FOLLOWS: 2/7/86.

- Plug #1 @ 7900' w/35 sx cement.  
 Plug #2 @ 5400' w/35 sx cement.  
 Plug #3 @ 5000' w/35 sx cement.  
 Plug #4 @ 4550' w/70 sx cement.  
 Plug #5 @ 1700' w/50 sx cement, Set 10 sx at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Dist. Superintendent

DATE 2/11/86

APPROVED BY

TITLE

OIL &amp; GAS INSPECTOR

DATE AUG 28 1987

CONDITIONS OF APPROVAL, IF ANY:

E