

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-27874 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. LG-814 |
| 7. Lease Name or Unit Agreement Name Woodpecker SY State |
| 8. Well No. 3 |
| 9. Pool name or Wildcat Saunders Permo Upper Penn |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| |
|--|
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER |
| 2. Name of Operator YATES PETROLEUM CORPORATION |
| 3. Address of Operator 105 South 4th St., Artesia, NM 88210 |
| 4. Well Location Unit Letter B : 660 Feet From The North Line and 1800 Feet From The East Line Section 21 Township 14S Range 33E NMPM Lea County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4214.5' GR |

| |
|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |
| NOTICE OF INTENTION TO: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> |
| SUBSEQUENT REPORT OF: |
| REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been temporarily abandoned. Propose to plug and abandon as follows:

1. Cut and pull 5-1/2" casing. CBL indicates top of cement at 7000'.
2. Spot a 100' cement plug inside and outside of 5-1/2" casing stub. WOC. Tag plug.
3. Spot a 100' cement plug across the top of the Glorieta at 5588'.
4. Spot a 100' cement plug across the 8-5/8" casing shoe at 4200'.
5. Spot a 100' cement plug across the top of the Yates at 2652'.
6. Spot a 100' cement plug across the 13-3/8" casing shoe at 452'.
7. Spot a 10 sack surface plug.
8. Install regulation abandonment marker.

NOTIFY OCD-HOBBS (505-393-6161) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE May 31, 1996

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-147

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: